



WRONG



CORRECT

CUT WITH RAZOR CUTTER
PART # CC1 OR CC2



OPTI-FLOAT[®]
LEVEL DETECTOR
FIBER CONNECTION
INSTRUCTIONS

DATE 03/19/09

DWG. 1 OF 1